

S/S/S - 1 Volume and 2 Tones - All 3 Coils Stock Wound Stock Polarity

Key




Solder joint



Ground connection.
Usually soldered to rear of volume pot

5 Way Selector Positions-

1. Bridge
2. Bridge & Mid in Parallel
3. Middle
4. Mid & Neck in Parallel
5. Neck



Bare Knuckle
PICKUPS